





SURVEY FINDINGS – Problems in 4 General Areas:

- Soil at seventeen sites had acidic soils with pH lower than 4.5
- Artesian dill holes with elevated levels of sulfate, copper, and other heavy metals
- Petroleum contamination detected around some drill sites
- Steel drill casings remaining above ground pose a danger to snow machines

| Initial Sites | Documented Sites | Sites with Environment al Issues | Sites with only Minor Issues | Fully Reclaimed Sites |
|------------------|---------------------|----------------------------------|------------------------------|-----------------------------|
| 1,355 | 107 (8%) | 44 (41%) | 27 (25%) | 36 (34%) |






DDH 4202 1Aug16

Petroleum contamination









GH05-60 1Aug16



 Artesian dill holes with elevated levels of sulfate, copper, and other heavy metals

Artesian Flow DDH 7386 2Aug16







Artesian Flow with drill cuttings DDH 9475 4Aug16





Artesian Flow with Drill Mud DDH 7380 2Aug16









DDH 4145 3Aug16

DDH 4232 3Aug16



Photo #14. Clay deposited in a dry depression by discharged drilling fluids.

*Drilling waste discharged to land. (ADNR inspection report June 2005)

What is the source of the contaminated soils?



Figure 4. Water and cuttings discharge on uplands.



2006 Pebble East Drill Site









Drill Waste Sumps
DDH 11540
220ct11



