

Introduced: 2/25/64  
Referred: Commerce and  
Labor and Management

1 IN THE HOUSE

BY MR. HAMMOND  
BY REQUEST

2

HOUSE BILL NO. 348

3

IN THE LEGISLATURE OF THE STATE OF ALASKA

4

THIRD LEGISLATURE - SECOND SESSION

5

A BILL

6

For an Act entitled: "An Act relating to electrical wiring."

7

BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF ALASKA:

8

\* Section 1. AS 08.40.100 is amended to read:

9

Sec. 08.40.100. EXCLUSION. (a) A person making an

10

electrical installation on residential property which is

11

owned by the installer or a member of his immediate family

12

and not intended for sale at the time of making the installa-

13

tion is not required to obtain a license.

14

(b) A person acting as an electrical contractor is not

15

required to obtain a license if fewer than three licensed

16

electrical contractors reside within 20 miles of the location

17

of the work, or if after diligent effort the person employing

18

him has been unable within a reasonable time to obtain the

19

services of a licensed electrical contractor without the pay-

20

ment of travel costs, per diem, or other surcharges above

21

the normal rate.

22

\* Sec. 2. AS 08.40 is amended by adding a new section to read:

23

Sec. 08.40.175. REQUIREMENT OF MINIMUM STANDARD BY

24

UTILITY. (a) Before supplying electricity to electrical

25

wiring not installed by a licensed electrical contractor, a

26

utility may, and in the case of work done by an unlicensed

27

person under the exemption provided for in sec. 100(b) of

28

this chapter, shall, inspect the electrical wiring. It shall

29

refuse to supply electricity to electrical wiring not

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29

installed in a safe manner. It may, in the case of wiring done under the exemption provided for in sec. 100(b) of this chapter, make and charge for such alterations as may be necessary.

(b) A utility is civilly liable for damages resulting from faulty wiring it should not have connected with under this section.