School District Major Maintenance



Rod Morrison Superintendent, Southeast Island School District

Southeast Island School District (2577 sq. miles)

REAA - Rural Education Attendance Area

- Kasaan School 1982 (temporary portable modular 20 yr)
- Whale Pass School 1985 (temporary portable modular - former logging camp community hub - 20 yr)
- 3. Port Alexander School 1982 / 1985
- 4. Thorne Bay School 1989
- 5. Naukati School 2005
- 6. Coffman Cove School 2009
- 7. Hollis School 2023







THORNE BAY SCHOOL UNDERGROUND STORAGE TANK REPLACEMENTS

CIP: Major Maintenance application submitted for 18 years.

FY26 rank: 75th

Requested in 2008: \$152,686

Amount Requested: \$1,182,737

Sediment from degrading tank and pipes clogged safety devices and flooded Thorne Bay Gym Boiler 2 and boiler room with over 150 gallons of diesel.

Diesel completely filled boiler combustion chamber and ran out front boiler door. Had this ignited, it could have destroyed the building and harmed the patrons in it (October 9, 2024)

The tank and or lines have clearly failed.







Thorne Bay K-12 Fire Suppression

CIP: Major Maintenance application submitted for 17 years.

FY26 rank: 38

Requested in 2009: \$1,014,255

THORNE BAY K-12 SCHOOL FIRE SUPPRESSION SYSTEM REPLACEMENT

Gym System completely inoperable since **March 12, 2024**

Amount Requested: \$1,375,904

During a gym light replacement project we found multiple lights that almost caught fire without the fire suppression system working.

Fire system is beyond repair and they no longer make parts to fix it.







Thorne Bay K-12 School HVAC Mechanical Control

CIP: Major Maintenance application submitted for 18 years.

FY26 rank: 22

Requested in 2011: \$877,083

This project will replace the failing 35-year-old pneumatic HVAC controls at the school with modern DDC control system for greater reliability and energy efficiency.

Amount Requested: \$1,496,950







Water main leak. Parts to fix it were discontinued 15 years ago.

SISD HVAC Mechanical Controls

FY 2008-2025: THORNE BAY K-12 SCHOOL MECHANICAL CONTROL UPGRADES

HVAC System failure - 36 yrs old, the F1 Supply Fan for Secondary Wing was completely destroyed when it wore out. (Installed June 24, 1988, inoperable on July 29, 2024)







SISD Thorne Bay School - Boiler Room

FY 2008-2025: THORNE BAY K-12 SCHOOL MECHANICAL CONTROL UPGRADES
Burst water fitting, only caught by happenstance. Flooded boiler room to school and boiler electrical was underwater. Clogged floor drains from pipe degradation and scaling.





Barry Craig Stewart Kasaan K-12 & Whale Pass K-12 School Renovation

Capital Improvement Project: Major Maintenance application submitted for 18 years.

FY26 rank: 26

Requested in 2008: \$558,615

Amount Requested: \$1,496,950

Furnace deteriorated to the point that flame burned through burn chamber at the Kasaan School.









Thorne Bay K-12 School Campus Roof Replacement

CIP: Major Maintenance application submitted for 14 years.

FY26 rank: 81

Requested in 2014: \$228,406

The roofing at the school and gym buildings has reached the end of its life span and is leaking.

Amount Requested: \$4,020,847

The roof leaks in several areas.

We often have to put garbage cans in classroom to catch the water.

This is a major roof problem that recently flooded the concession stand and the room. This leak was discovered on a weekend.





Port Alexander K-12 School Upgrades

Capital Improvement Project: Major Maintenance application submitted for 18 years.

FY26 rank: 60

Requested in 2008: \$110,152

PORT ALEXANDER K-12 SCHOOL DOMESTIC WATER SYSTEM PIPE REPLACEMENT

Amount Requested: \$1,861,247

Laundry Room floor has rotted out and has been repaired several times. As a result, multiple widespread plumbing leaks have occurred inside the insulated floor structure, soaking main beams and causing structural integrity issues. (June 7, 2024 and more October 10, 2024)







All of our schools also serve the communities as gathering spots and emergency shelters.









71

Education has the potential to be a great equalizer and, with improved efforts, Alaska can be working towards making it more equitable for all.

Thank you! Questions?

Mr. Rod Morrison rmorrison@sisd.org

