

March 14, 2014

RE: Alaska Capitol Seismic Retrofit and Exterior Renovation Architecture Interiors Construction Management Representative Mike Hawker, Chair Legislative Council Alaska State Legislature 120 4th Street, State Capitol, Room 502 Juneau, AK 99801 1935 Founded as H.B. Foss Company Dear Representative Hawker: 1945 In an effort to refine the construction cost and to better evaluate alternative Foss & Malcolm methods and material as well as further investigate cost saving possibilities 1949 we propose reducing the construction during the 2014 season and dedicating Foss, Malcolm & Olsen more effort during this time to evaluating cost saving opportunities. We have 1951 identified several possible ways to reduce construction cost; we need to Foss & Olsen evaluate these during the demolition of portions of the exterior walls to 1956 determine if they are feasible to incorporate into the approach to the project. Foss, Olsen & Sands At the completion of the 2014 construction season we will provide a revised 1958 cost proposal to the Council for the remaining work. Olsen & Sands 1969 The underlying consideration during the investigation and evaluation period is Sands & Ackley to maintain the purpose of the project to upgrade the building for seismic 1974 resistance, renovate the exterior envelope and replace the heating system Ackley & Associates throughout the building. Any cost reduction opportunities that are adopted will 1979 be evaluated in terms of the cost/benefit to the project. The goal is to Ackley/Jensen renovate the building structure and exterior to last many more decades. Architects, Inc. 1985 The approach for the 2014 construction season is to concentrate on the west Jensen Douglas (Main Street) side of the building and to construct the infill areas on the 3rd, Architects, Inc. 4th and 5th floors on either side of the main stair/elevator area. The work on

where work will take place during 2014.

the west side will involve removal of the brick, stone and terracotta in the

exterior walls and the windows. By doing this we can determine if the interior finishes in some of the rooms can be retained. If this is possible significant savings can be achieved and disruption will be minimized. Since the west side is representative of the rest of the building we can project the findings to the work in the following seasons. Attached is a drawing illustrating the areas

1997 Jensen Yorba Lott, Inc.

522 West 10th Street Juneau, Alaska 99801 Tel.: 907.586.1070 Fax: 907.586.3959 jensenyorbalott.com Rep. Mike Hawker March 14, 2014 Page 2

The structural work will be completed on the west side and the new windows will be installed. The work will also include replacing the heating piping and convectors and restoring the interior finishes where needed.

The work related to the infill areas will consist of the structural floor and roof system but will not include the final exterior closure or interior work. Constructing the new floors in the in-fill areas will not only provide valuable information for the following year, but it will allow a more efficient construction sequence since the structural work will be completed avoiding a potential "bottle neck" between trades working in the courtyard.

The proposed cost for the 2014 construction season is \$5.8 million. This also includes a contingency, the Contractors fee and a portion of the Incentive Fee. This format is as outlined in the Request for Proposals that was issued last fall to select the Construction Manager/General Contractor. The work done by the CM/GC will be paid on a time and materials basis and will be monitored monthly for consistency with the contract.

Sincerely,

Wavne

cc: Pam Varni, Jeff Goodell

G:_Projects\12053\7Construction contract Phase II\2014 Construction Contract.docx





