

State of Alaska Department of Education & Early Development Finance & Support Services/ Facilities

# FACT SHEET

## Chalkyitsik K-12 School Water Tank Replacement Yukon Flats School District

## **CIP** Application History

Year	CIP FY	Title	DEED Rank	Eligible Amount \$	Participat'g Share \$	State Share \$
2010	FY11	Chalkyitsik Water Tank Replacement	57	\$1,003,757	\$20,075	\$983,682
2011	FY12	Chalkyitsik Water Tank Replacement	68	\$1,006,322	\$20,126	\$986,196
2012	FY13	Chalkyitsik Water Tank Replacement	52	\$1,185,789	\$23,716	\$1,162,073
2013	FY14	Chalkyitsik Water Tank Replacement	51	\$1,185,789	\$23,716	\$1,162,073
2014	FY15	Chalkyitsik K-12 School Water Tank Replacement	60	\$1,351,847	\$27,037	\$1,324,810
2015	FY16	Chalkyitsik K-12 School Water Tank Replacement	56	\$1,393,754	\$27,875	\$1,365,879
2016	FY17	Chalkyitsik K-12 School Water Tank Replacement	49	\$1,247,680	\$24,954	\$1,222,726
2017	FY18	Chalkyitsik K-12 School Water Tank Replacement	64	\$1,263,276	\$25,266	\$1,238,010
2018	FY19	Chalkyitsik K-12 School Water Tank Replacement	31	\$1,272,216	\$25,444	\$1,246,772

## BACKGROUND

#### FY2019 CIP Project Description:

This project provides for replacement of a leaking water tank serving 16,687 square feet of facilities built between 1967 and 1988. The scope of work includes disposal of the existing 100,000 gallon wood-stave tank and installation of a replacement steel tank including an insulated gravel pad and hydronic tank heating to prevent freezing.

## **CHRONOLGY OF EVENTS**

- Project was first submitted by the Yukon Flats School District (YFSD) for the FY2011 CIP application cycle.
- District continued to submit a project application or request for reuse of scores through the FY2019 CIP cycle.
- The YFSD preventive maintenance and facility management program was not certified following the 2019 (FY2020 CIP) site visit, making the district ineligible to submit CIP applications until corrected. Deficiencies were found in maintenance management, energy management, and maintenance and custodial training.

Fact Sheet Chalkyitsik K-12 School Water Tank Replacement Page 2 of 2

- Since May 2019, the Yukon Flats School District has made some minimal efforts to address deficiencies noted in their training program. Deficiencies in maintenance management and energy management have not been addressed—at least to the department.
- Regular outreach has occurred from the department regarding opportunities for provisional compliance.

## ACTIONS

The department will continue to work with the Yukon Flats School District to achieve compliance with requirements for maintenance and facilities management and eligibility for submission of CIP applications.

## RECOMMENDATIONS

See Actions above.